







Model 型號	AQ-08-950	AQ-12-950	AQ-16-1000	AQ-22-1000	AQ-27-1000
For Tap 攻牙能力	M2~M8	M3~M12	M3~M16	M3~M22	M3~M27
Speed(rpm) 主軸轉速	700	400	300	120/300	70/220
Weight(kg) 重量	18	18	29	29	29
Work Range(mm) 工作範圍	Rmax 950 Rmin 10	Rmax 950 Rmin 10	Rmax 1000 Rmin 10	Rmax1000 Rmin 10	Rmax1000 Rmin 10




Model 型號	AS-08 / II	AS-12 / II	AS-16 / II
For Tap 攻牙能力	M2~M8	M3~M12	M3~M16
Speed(rpm) 主軸轉速	700	400	300
Weight(kg) 重量	20	20	22
Work Range(mm) 工作範圍	Rmax1400 Rmin 200	Rmax1400 Rmin 200	Rmax1400 Rmin 200



Model 型號	AT-08 / I	AT-12 / I	AT-16 / I
For Tap 攻牙能力	M2~M8	M3~M12	M3~M16
Speed(rpm) 主軸轉速	700	400	300
Weight(kg) 重量	19	19	24
Work Range(mm) 工作範圍	Rmax1600 Rmin 500	Rmax1600 Rmin 500	Rmax1600 Rmin 500



Model 型號	AT-08 / II	AT-12 / II	AT-16 / II
For Tap 攻牙能力	M2~M8	M3~M12	M3~M16
Speed(rpm) 主軸轉速	700	400	300
Weight(kg) 重量	23	23	27
Work Range(mm) 工作範圍	Rmax1900 Rmin 200	Rmax1900 Rmin 200	Rmax1900 Rmin 200



Model 型號	AT-20 / II	AT-22 / II	AT-27 / II
For Tap 攻牙能力	M3~M20	M3~M22	M3~M27
Speed(rpm) 主軸轉速	150/400	120/300	70/220
Weight(kg) 重量	39	39	39
Work Range(mm) 工作範圍	Rmax1900 Rmin 200	Rmax1900 Rmin 200	Rmax1900 Rmin 200

STANDRD ACCESSORIES:

- Air tapping spindle
- Parallel arm
- Table mounting column

《 TTYPE I 》

- Air unit
- Choose any six safety clutch tapping adapters

《 TTYPE II 》

- Air tapping spindle
- Parallel arm
- Table mounting column
- Air unit
- Choose any six safety clutch tapping adapters
- Radial jib